## **Industrial Arbors**

Easily converts a drill press, milling machine, lathe or CNC machine to accept cutters, therefore increasing their versatility, and capacity to cut up to 3 times larger diameter holes than solid drills allow.

Also will suit most portable magnetic drilling machines with a morse taper fitting as a spare or replacement arbor.

Available with or without an external coolant ring, which allows cutting oil to be internally fed through the tool, resulting in a cleaner hole finish, positive ejection of the centre slug and prolonged cutter life.





With radial arm drill

With magnetic drill

#### Standard, without External Coolant Ring

PART NUMBER	DESCRIPTION
JEIARBOR-2MT	2MT Cutter arbor, to suit 19 mm shank cutters
JEIARBOR-3MT	3MT Cutter arbor, to suit 19 mm shank cutters
JEIARBOR-4MT	4MT Cutter arbor, to suit 19 mm shank cutters
JEIARBOR-3MT/32	3MT Cutter arbor, to suit 1-1/4" (31.75 mm) shank cutters
JEIARBOR-4MT/32	4MT Cutter arbor, to suit 1-1/4" (31.75 mm) shank cutters
JEIARBOR-5MT/32	5MT Cutter arbor, to suit 1-1/4" (31.75 mm) shank cutters



### With External Coolant Ring

PART NUMBER	DESCRIPTION
JEIARBOR-2MTC	2MT Cutter arbor with external coolant ring, to suit 19 mm shank cutters
JEIARBOR-3MTC	3MT Cutter arbor with external coolant ring, to suit 19 mm shank cutters
JEIARBOR-4MTC	4MT Cutter arbor with external coolant ring, to suit 19 mm shank cutters
JEIARBOR-3MT/32C	3MT Cutter arbor with external coolant ring, to suit 1-1/4" (31.75 mm) shank cutters
JEIARBOR-4MT/32C	4MT Cutter arbor with external coolant ring, to suit 1-1/4" (31.75 mm) shank cutters
JEIARBOR-5MT/32C	5MT Cutter arbor with external coolant ring, to suit 1-1/4" (31.75 mm) shank cutters



#### **Quick Change Morse Taper Cutter Arbor**

Secures (3/4") Shank Cutters without the need of allen screws Quick, accurate changing of cutter Includes Integral cooling system Available in 2 and 3 Morse Taper Suitable For Magnetic Drilling Machines or Radial Arm Drills

PART NUMBER	DESCRIPTION
JEIARBOR2MTC-QR	Industrial Arbor, Quick release type 2 Morse Taper
JEIARBOR3MTC-QR	Industrial Arbor, Quick release type 3 Morse Taper

# **Morse Taper Sleeves**

Designed to adapt morse taper drills and arbors to fit the required taper socket.

PART NUMBER	DESCRIPTION
JEIMTS-2-1	Morse taper sleeve, 2MT shank reducing for 1MT tooling
JEIMTS-3-1	Morse taper sleeve, 3MT shank reducing for 1MT tooling
JEIMTS-3-2	Morse taper sleeve, 3MT shank reducing for 2MT tooling
JEIMTS-4-2	Morse taper sleeve, 4MT shank reducing for 2MT tooling
JEIMTS-5-3	Morse taper sleeve, 5MT shank reducing for 3MT tooling
JEIMTS-5-4	Morse taper sleeve, 5MT shank reducing for 4MT tooling

